



DEPARTMENT OF  
WATER RESOURCES

# CACHE CREEK AREA *Fact Sheet* **Site 3.9**

Critical Levee Erosion Site

## Emergency Levee Repairs

### Location

River: Cache Creek

Levee Mile: 3.9

Latitude/Longitude:

38.727625/-121.780335

Nearest Impact Area:

Woodland

County: Yolo

Bank: Left

### Type of Damage

Bank erosion

### Length of Repair

430 feet (approximate)

### Repair Type

Setback levee

### Lead Agency

Department of Water Resources

**For further information,  
please contact:**

**Elizabeth Scott**  
**DWR Public Affairs Office**  
**(916) 835-5344**  
**[leveerepair@water.ca.gov](mailto:leveerepair@water.ca.gov)**

DEPARTMENT OF WATER RESOURCES  
PO Box 942836, Sacramento, CA 94236

**[www.levees.water.ca.gov](http://www.levees.water.ca.gov)**

